



Time Period:	November of two w	17-29, 2014 (eeks)	Project No:	1305
Rain Days/Weather Conditions:		Rained 1.6" on Sunday night-Monday morning (11/16-11/17). Also rained 0.75" Monday (11/23) (Burkesville gauge).		
Personnel on-site:  Equipment on-site:		EcoGro/Ridgewater: Tony Berry, Tom Cutter, Eric Dawalt, Jon Linder, Brad Redmon, & Chad Relinski.  Stantec: N/A  Komatsu PC 160 w/ hyd. thumb, PC 360 w/ hyd. thumb, Terex TA27		
		articulating dump truck, Bobcat T300 skid steer, Sunbelt JCB pad foot compactor (demobilized on 11/25), & Morooka 2200 VD Tracked Dump Truck		
Material deliveries to project site:		■ N/A		
Work performed the past two weeks:		<ul> <li>Did not work Monday(11/17) or Monday (11/24) due to rain.</li> <li>Moved all tree piles off of Corps Site #1.</li> <li>Started construction of braided channel RT Sta. 111+00 to 113+00.</li> <li>Hauled rock from Disposal area and stockpiled at ~Sta. 114+00 for channel construction.</li> <li>Excavated for floodplain and channel upstream of Campground Road (~Sta. 113+00 to 114+00) and hauled clay to ravine.</li> <li>Built ravine compacted clay fill up to ~elevation 586.0'.</li> <li>Built rock spillway up to ~elevation 583.5'</li> <li>Constructed compacted clay Ground Water Dam from ~ LT. Sta. 106+60 to 107+80.</li> </ul>		
Erosion & sediment controls installed/maintained:		<ul> <li>Dewatered and removed rock check dams at downstream end of ravine fill before beginning excavation of plunge pool.</li> <li>Constructed plunge pool in ravine is serving as a sediment basin.</li> </ul>		
Work scheduled for next week:		<ul> <li>Begin building Floodplain Berm to allow finishing construction of ravine rock spillway ~LT Sta. 106+00 to 106+60.</li> <li>Finish rock spillway in ravine stream crossing ~LT Sta. 106+00 to 106+60 up to elevation 587.6'.</li> <li>Construct braided channel from ~Sta. 110+00 to 113+50.</li> <li>Fill sinkhole in ravine with rock up to bedrock step elevation and then add a layer of geotextile and compacted clay (If weather allows).</li> <li>Start building confluence bar downstream of bridge.</li> </ul>		
Work planned for two weeks ahead:		Finish channel from ~Sta. 110+00 to 113+50.		
General Comme	ents:	soil from > EcoGro/	onstruction, the USACE excav Site #3. They did not work 11. Ridgewater did not work Thurs iving holiday.	/23 thru 11/29.
Prepared by: E	ric Dawalt, P.E.	<b>Date</b> : 11-29-14		





Pictures from the past week's construction:



Constructing braided channel . (Photograph taken from ~RT Sta. 111+50)



Finished construction of compacted ravine clay core to elevation ~586.0' (Photograph taken from Ravine Footbridge)







Constructing ravine rock spillway with geotextile and rock (Photograph taken from ravine compacted clay core).



Ravine rock spillway built up to elevation 583.5' with geotextile and rock. (Photograph taken 11/22 at ~180' LT Sta.106+30).







Constructing clay Ground Water Dam to bedrock from ~ LT. Sta. 106+60 to 107+80 (Photograph take from left end of ravine footbridge). Ponded water is in ravine.



Aspen Construction excavating from Site #3. (Photograph was taken from existing gravel road at ~Sta. 157+50 looking upstream).